

ACCOUNTS OFFICE







Chlor

**FOX**  
**DRY POWDER**  
**FIRE EXTINGUISHER**

**INSTRUCTIONS**

**Maintenance**

- Check and Recharge as per IS 2013 (2000).
- Inspect periodically and ensure that there is no pressure drop.
- Lock the and Wipeout area as instructed.

**Precaution**

- Keep safe under pressure.
- Do not tamper with the shell.
- Break the Safety Seal only in case of fire.
- Do not rely on partially used or discharged extinguisher.

**Inspection**

- The Seal and Tamper Indicators are not broken or intact.
- It is full (by weighing or filling).
- It is not abraded, damaged, corroded, leaking or has Chemical Hazards.
- The Pressure Gauge (if any) and Indicator is in the operable range or position.

**Records**

- Record Maintenance Date and Recharge Date as attached to the tag.

**RECHARGE**

Capacity: 4 Kg  
Service Pressure: 18 Bar  
Gross Weight: 6.32 to 6.42 Kg  
Tested at: 30 Kg/cm<sup>2</sup>  
Filling tolerance: ± 2 % by mass

**RECHARGE**

Capacity: 4 Kg  
Service Pressure: 18 Bar  
Gross Weight: 6.32 to 6.42 Kg  
Tested at: 30 Kg/cm<sup>2</sup>  
Filling tolerance: ± 2 % by mass

**RECHARGE**

Capacity: 4 Kg  
Service Pressure: 18 Bar  
Gross Weight: 6.32 to 6.42 Kg  
Tested at: 30 Kg/cm<sup>2</sup>  
Filling tolerance: ± 2 % by mass

**FIRE SERVICE**

CONTACT NO: 022-229401



Operating Temp: +10°C to +35°C

Capacity: 4 Kg  
Service Pressure: 18 Bar  
Gross Weight: 6.32 to 6.42 Kg  
Tested at: 30 Kg/cm<sup>2</sup>  
Filling tolerance: ± 2 % by mass

Manufacturer: **INDIA PVT. LTD**









