

MOIN ARCHITECTS

Architect & Interior Designers
Shantipuram , Delapeer Bareilly (U.P.).

Certificate²

The copies of approved site Plan and Building Plans in respect of application submitted by **Mr. Harendra Kumar S/o Shri Bijendra Singh R/o 72-1 Takhsila Colony ,Garh road Meerut, District – Meerut (U.P.)** who is an Applicant for establishment of new Technical Institution **AIMS Pharmacy College** at NH-24 Bhagwanpur Khadar Near Kakather Crossing, Gajraula, District – Amroha, Pin – 244235, (U.P.) were provided to me by **Shree Educational & Welfare Trust** for verification regarding their authenticity and appropriateness.

Details of Site Plan and Building Plans:

Plans approved by	Jila Panchayat, Amroha (U.P.)
Approval Number	Memo/Nirman/625/20
Date of Approval	19-11-2020

I hereby certify that:

1. The Competent Authority has approved the site Plan and Building Plans of an educational Institution at the proposed site mentioned above is **Jila Panchayat, Amroha (U.P.)**.
2. I have verified the above-mentioned site Plan and Building Plans from the Office of **Jila Panchayat, Amroha (U.P.)**.
3. The above-mentioned site Plan and Building Plans have been approved by the Competent Authority.
4. The above-mentioned site Plan and Building Plans are authentic.
5. Construction of Building admeasuring with the following details has been completed in all respects as per the approved Building Plan.

S. No.	Room No	Room type (mention Class room / Lab / Toilet, etc.)	Carpet area (in sq m2)	Completion of Flooring	Completion of Walls and painting	Completion of Electrification and lighting
A. Instructional Area (INA) (Carpet Area) in m2						

1	I	Class Room	78.10 80.00 78.10 80.00 89.63 89.63	495.46	Completed	Completed	Completed
2	I	Tutorial Room	62.43		Completed	Completed	Completed
3	I	Language & Computer Lab	78.10		Completed	Completed	Completed
4	I	Laboratory(s)	75.00, 75.97, 76.43, 75.00 75.00 75.00 75.00 75.00 75.00	=752.40	Completed	Completed	Completed
5	I	Machine Room	81.08		Completed	Completed	Completed
6	I	Animal House	80.00		Completed	Completed	Completed
7	I	Museum	60.48		Completed	Completed	Completed
8	I	Library	158.11		Completed	Completed	Completed
9	I	Seminar Hall	136.48		Completed	Completed	Completed
B. Administrative Area (ADA)							
10	I	Principal Room	33.01		Completed	Completed	Completed
11	I	Board Room	25.69		Completed	Completed	Completed
12	I	Office	17.35 17.35		Completed	Completed	Completed
13	I	Department Office	26.10		Completed	Completed	Completed
14	I	Faculty Room	68.70		Completed	Completed	Completed

15	I	Reception & Waiting Lobby	105.26 74.78	Completed	Completed	Completed
16	I	Central Store	24.38	Completed	Completed	Completed
17	I	Maintenance Room	11.23	Completed	Completed	Completed
18	I	Security Room	10	Completed	Completed	Completed
19	I	House Keeping	11.41	Completed	Completed	Completed
20	I	Pantry for Staff	23.33	Completed	Completed	Completed
21	I	Examination Control Room	35.14	Completed	Completed	Completed
22	I	Placement Office	53.07	Completed	Completed	Completed
C. Amenities Area (AMA)						
23	I	Boys Common Room	78.76	Completed	Completed	Completed
24	I	Girls Common Room	78.76	Completed	Completed	Completed
25	I	Cafeteria	155.50	Completed	Completed	Completed
26	I	Stationary	16.14	Completed	Completed	Completed
27	I	First AID	12.27	Completed	Completed	Completed
28	I	Toilet (Ladies & Gents)	150	Completed	Completed	Completed

Details of the Occupancy/ Completion Certificate/ Building License/ Form D


Certificate approved by	Office Executive Engineer, Amroha (U.P.)
Approval Number	288/09 B
Date of Approval	19/01/2022

Structural Stability Certificate

Certificate approved by	Office Executive Engineer, Amroha (U.P.)
Approval Number	288/09 B
Date of Approval	19/01/2022

I hereby certify that:

1. The Competent Authority has approved the Occupancy/ Completion Certificate/ Building License/ Form D/ Structural Stability Certificate mentioned above is **Office Executive Engineer, Amroha (U.P.)**.
2. I have verified the above-mentioned Certificates from the Office of **Office Executive Engineer, Amroha (U.P.)**.
3. The above-mentioned Certificates have been approved by the Competent Authority.
4. The above-mentioned Certificates are authentic.

Signature of the Architect		Seal
Name of the Architect	Moinuddin Architect	
Registration No	CA/2018/95713	
Date :	Place :
